Maryland Historical Trust

Maryland Inventory of Historic Properties Number: Name: And Andrew Roll Roll Roll Roll Roll Roll Roll Rol	land State Highway Administration as part rust with eligibility determinations in	
MARYLAND HISTORICAL TRUST		
Eligibility RecommendedX	Eligibility Not Recommended	
Criteria:ABCD Considerations:A	BCDEFG _None	
Comments:		
Reviewer, OPS:Anne E. Bruder	Date:3 April 2001	
Reviewer NR Program: Deter F Kurtze	Date: 3 April 2001	

Maryland Inventory of Historic Properties Historic Bridge Inventory Maryland State Highway Administration Maryland Historical Trust

SHA Bridge No. G-111 Name: Avilton Lonaconing Road over Savage River **Location:** Street/Road Name and Number: Avilton Lonaconing Road City/Town: Avilton Vicinity X County: Garrett Ownership: __State X County __Municipal __Other This bridge projects over: __Road__Railway X Water__Land Is the bridge located within a designated district: yes X no _NR listed district_NR determined eligible district _locally designated_other Name of District **Bridge Type:** _Timber Bridge _Beam Bridge_Truss-Covered_Trestle _Timber-and-Concrete _Stone Arch _Metal Truss _Movable Bridge _Swing _Bascule Single Leaf_Bascule Multiple Leaf __Vertical Lift_Retractile_Pontoon _Metal Girder _Rolled Girder _Rolled Girder Concrete Encased _Plate Girder _Plate Girder Concrete Encased Metal Suspension _Metal Arch _Metal Cantilever X Concrete X Concrete Arch Concrete Slab Concrete Beam Rigid Frame _Other Type Name_

G-1-A202

Describe Setting:

Bridge G-111 carries Avilton Lonaconing Road over the Savage River in Garrett County. Avilton Lonaconing Road runs north-south over the northern flowing Savage River. The bridge is surrounded by sparse residential development and forest.

Describe Superstructure and Substructure:

Bridge G-111 is a single span filled concrete arch bridge. The length of the bridge is 72 feet 10 inches with a clear span measuring 50 feet at the springline. The spandrel walls are approximately 25 feet wide. A 5 by 4-inch ledge runs the entire length of the bridge. There is a clear roadway width of 14 feet 2 inches, with an overall width of 16 feet 6 inches. According to a 1995 inspection report the concrete arch has slight vertical cracking on each side with light damp efflorescence. However on the southern spandrel wall at the apex of the arch there is a crack which extends from the center of the arch into the southern parapet. The bridge is in critical condition, with a sufficiency rating of 58.5.

Bridge G-111 has its original parapets. The parapets are approximately 60 feet long and 3 feet high on both the eastern and western sides of the bridge. The parapet is a single section with no expansion joints. Each parapet has 8 symmetrical incised panels. Each panel is approximately 4 feet long by 22 inches wide and are approximately 10 inches apart. At either end of each parapet is a solid endblock. It does not appear that these 6-foot by 3-foot blocks were incised. The parapets have shifted up to 4 inches. The southern parapet at the center of the bridge has a large crack.

Discuss Major Alterations:

At an unknown date the county maintenance crews used tiebolts on the upstream and downstream sides of the eastern spandrel wall. The spandrel wall was shifting and the tiebolts assist in the prevention of shifting.

History:

When Built: 1909

Why Built: Expansion of infrastructure in Garrett County

Who Built: Luten Bridge Company, York, Pa.
Who Designed: Luten Bridge Company, York Pa.
Why Altered: Prevention of shifting in the spandrel wall.

Was this bridge built as part of an organized bridge building campaign? No, this bridge was not built as

part of an organized bridge building campaign.

Surveyor Analysis:

This bridge may have NR significance for association with:

XA Events Person XC Engineering/Architectural

This bridge was determined eligible by the Interagency Review Committee in February 1996.

Was this bridge constructed in response to significant events in Maryland or local history?

Yes, as Garrett County expanded, it needed to improve its infrastructure. Founded in 1871, Garrett County relied heavy on the railroad and the National Pike as its transportation corridors even as early the first decade of the twentieth century. As the county expanded in population and made inroads into mineral exploration the county infrastructure needed improvement. The Garrett County Commissioners contracted the job to the Luten Bridge Company of York, PA, which was incorporated in 1909 as a contracting concern specializing in the designs of Daniel Luten. It grew to be the largest of Luten's loosely affiliated corporations and operated offices in Clarksburg, WV; Concord, NH; Columbus, OH; Chatsworth, GA; and Syracuse, NY. Daniel Luten

G-I-A-202

specialized in the reinforced concrete bridges. His designs dominated the market and were copied (under patent protection) and used throughout the eastern United States.

Is the bridge located in an area that may be eligible for historic designation and would the bridge add to or detract from historic and visual character of the possible district?

No, the bridge is not located in an area that is eligible for historic designation.

Is the bridge a significant example of its type?

Yes, this bridge has a marble plaque that dates the bridge to 1909. The plaque also lists the builder as the Luten Bridge Company of York, PA. This was the parent company of Daniel Luten, one of the nation's pioneers in concrete bridge building. This bridge's construction date is identical to the year that his company was founded. Bridge G-111 appears to be among the Luten Company's first bridges constructed.

Does the bridge retain integrity of the important elements described in the Context Addendum?

Although the bridge appears to be experiencing some shifting within the arch, it still retains the integrity of its character defining elements.

Should this bridge be given further study before significance analysis is made and why?

Yes, its is important to know how many of Luten's earliest structures are remaining throughout the region. There are very few that can be documented with a construction marker.


Bibliography:		
County inspection/bridge files	X	SHA inspection/bridge files
Other (list):		

Surveyor:

Name: Stacie Y. Webb Date: September 1995

Organization: State Highway Admin. Telephone: (410) 545-8559

Address: 707 N. Calvert Street, Baltimore, Maryland Edited by P.A.C. Spero & Company, December 1996





BR# 706-1110 G-T-A202 Over SAVAGE RIVER (-ARRE- CO, MC TAVE VING Vield de 412 EAST APPROACH 15: 5



384 20611110 G-I-A-202 DVER SAVAGE RIVER GARREN On Md. DAVE EINE 1/26/28 9,44

WEST APPROACH

245

Built for the Commissioners GARRETT CO. 1009. By the Luten Bridge (a. Yorli. Pa.

G-T-A-202 FR# 20611110 OVER SAVAGE RIVER LAKET CONNE TO A 1/2 REPORT -SUL PLAQUE ON NURTH PARAPET

3015



G-T-A-202 7 L+ 2061 5 DUEC SAVAGE THEE GARLET CO INT. L. Comment < ---NURTH ELEVATION (UPSTREAM)



17 # 206 W V 6-T-A-202 DVER SAVAGE RIVER ELPRET CONT SOUTH ELEVATION (DOWNSTREAM)

The same